



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: August 6, 2009

Reviewed: LK

Mine Name: Black Rock Quarry	Permit Number: M0270088
Operator Name: Alloc Fine Aggregates	Inspection Date: 04/22/2009
Inspector(s): Tom Munson	Time: 9:00 am
Other Participants:	Mine Status: Suspended

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: Current amount held is \$21,900 with one more payment owed in October 2009 of \$4,300 for a total bond of \$26,900 for the current disturbance foot print.

Permit fee: Current.

Purpose of Inspection:
A routine site inspection.

Inspection Summary:
The site was inactive at the time of inspection and it appeared that it has not been active for a period of time. No new disturbance since the last inspection.
No Photos taken.

Conclusions and Recommendations:
The final transfer of the site needs to be completed by the Division and a letter sent to the Operator with a final approval of the transfer.
No Photos taken

Inspector's Signature [Signature]

TM:vs

cc: Alloc Fine Aggregates
Jerry_mansfield@blm.gov

O:\M027-Millard\M0270088-BlackRock\inspections\insp-04222009.doc